

**AD337A/ AD338A 2-Port
Gigabit Ethernet Card
on HP-UX 11i v2
of June 2007
Release Notes**

IEther-00 Software Version B.11.23.0706

June 2007

Printed in U.S.A.



Legal Notices

The information in this document is subject to change without notice.

Hewlett-Packard makes no warranty of any kind with regard to this manual, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Hewlett-Packard shall not be held liable for errors contained herein or direct, indirect, special, incidental or consequential damages in connection with the furnishing, performance, or use of this material.

Warranty

A copy of the specific warranty terms applicable to your Hewlett-Packard product and replacement parts can be obtained from your local Sales and Service Office.

Restricted Rights Legend

Use, duplication or disclosure by the U.S. Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 for DOD agencies, and subparagraphs (c) (1) and (c) (2) of the Commercial Computer Software Restricted Rights clause at FAR 52.227-19 for other agencies.

HEWLETT-PACKARD DEVELOPMENT COMPANY L.P.
20555 S.H. 249
Houston, Texas 77070

Use of this document and any supporting software media supplied for this pack is restricted to this product only. Additional copies of the programs may be made for security and back-up purposes only. Resale of the programs, in their present form or with alterations, is expressly prohibited.

Copyright Notice

Copyright © 1997-2007 Hewlett-Packard Development Company L.P.
Reproduction, adaptation, or translation of this document without prior written permission is prohibited, except as allowed under the copyright laws.

AD337A/ AD338A 2-Port Gigabit Ethernet Card on HP-UX 11i v2 of June 2007 Release Notes

Updated Configuration Scripts Required for AD337A and AD338A

The following information describes issues with the HP-UX-based AD337A/ AD338A 2-Port Gigabit Ethernet cards which use the driver IETHER-00 Software Version B.11.23.0706. The IETHER-00 software bundle, which is built into the OE, contains the driver called iether.

The AD337A and AD338A cards running on HP-UX 11i v2 require updated scripts hpiether and hpiether.init to fix a known problem. Multiple configuration changes involving any of the following parameters fail:

- Autonegotiation on/off
- Speed
- Flow control

This problem only occurs with the AD337A and AD338A cards.

Temporary Workaround until September 2007 quarterly HP-UX Release

Obtain the scripts hpiether and hpiether.init from the HP IT Resource Center: <http://itrc.hp.com>. Install them and reboot.

Long Term solution -- after September 2007

This known problem will be fixed in the September 2007 quarterly HP-UX release. When the September 2007 version of HP-UX 11i v2 is available, HP recommends installing the September 2007 update release of HP-UX 11i v2 to permanently solve this problem.

