

GigEther-01 (igelan) Gigabit Ethernet Driver Release Notes for HP-UX 11i v3 GigEther-01 Software Version B.11.31.0903

HP Part Number: 5992-4704
Published: March 2009
Edition: 1.1



Legal Notices

© Copyright 2009 Hewlett-Packard Development Company, L.P.

Confidential computer software. Valid license from HP required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing here should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Table of Contents

| | |
|--|---|
| 1 GigEther-01 (igelan) Gigabit Ethernet Driver for HP-UX 11i v3, March 2009 Release..... | 5 |
| What Is In this Version..... | 5 |
| Related Document..... | 5 |

1 GigEther-01 (igelan) Gigabit Ethernet Driver for HP-UX 11i v3, March 2009 Release

This document contains information about GigEther-01 (igelan) Gigabit Ethernet Driver supported on HP-UX 11i v3 for the March 2009 release.

This document discusses the following topics:

- “What Is In this Version” (page 5)
- “Related Document” (page 5)

What Is In this Version

The following information describes the updates to the HP-UX-based Gigabit ethernet driver called igelan. The `GigEther-01` software bundle, which is loaded into the operating environment (OE), contains the igelan driver.

The March 2009 version of the HP-UX 11i v3 `GigEther-01` software bundle contains the following defect fix:

- QXCR1000883926 The igelan driver is enhanced to log the Producer and the Consumer index of the Receive ring under following conditions:
- When the HP-UX system panics
 - When the HP-UX system is TOC'd

Related Document

For some known command differences when igelan is used on the HP BL860c or BL870c Server Blades, see *HP-UX 11i v2 Network Command Differences when used with HP BL860c/BL870c Server Blades*.

For complete information on what is new or changed in GigEther-01 (igelan) for the HP-UX 11i v3 operating system, see the “I/O Subsystem” subsection of the *HP-UX 11i Version 3 Release Notes* at <http://www.docs.hp.com>.