

GigEther-00 (gelan) Gigabit Ethernet Driver Release Notes for HP-UX 11i v3 GigEther-00 Software Version B.11.31.0903

HP Part Number: 5992-4708
Published: March 2009
Edition: 1



Legal Notices

© Copyright 2009 Hewlett-Packard Development Company, L.P.

Confidential computer software. Valid license from HP required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing here should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Table of Contents

1 GigEther-00 (gelan) Gigabit Ethernet Driver for HP-UX 11i v3, March 2009 Release.....	5
What Is In this Version.....	5
Related Document.....	5

1 GigEther-00 (gelan) Gigabit Ethernet Driver for HP-UX 11i v3, March 2009 Release

This document contains information about GigEther-00 (gelan) Gigabit Ethernet Driver supported on HP-UX 11i v3 for the March 2009 release.

This document discusses the following topics:

- “What Is In this Version” (page 5)
- “Related Document” (page 5)

What Is In this Version

This document describes the changes made to the HP-UX-based GigEther-00 (gelan) Gigabit Ethernet Driver. The gelan driver is shipped with the GigEther-00 software bundle, which is a part of the Operating Environment (OE).

The March 2009 version of the HP-UX 11i v3 GigEther-00 software bundle contains the following defect fixes:

- | | |
|----------------|---|
| QXCR1000818617 | The gelan driver is enhanced to support 64 KB Operating System (OS) page size. |
| QXCR1000811814 | The olrad script, <code>/usr/sbin/olrad.d/gelan</code> , is modified to check whether any vswitches are associated with the gelan driver before deleting the module. |
| QXCR1000587490 | The <code>nwmgr_gelan</code> (1M) manpage specifies that the default package size of the default test frame for the diagnose operation is 100 bytes instead of MTU-3. This defect is fixed. |

Related Document

For related information, see the “I/O Cards and Networking Software” web page at <http://docs.hp.com/en/netcom.html>.