

# IEther-00 (iether) B.11.31.0810 Gigabit Ethernet Driver Release Notes HP-UX 11i v3

HP Part Number: 5992-5754  
Published: October 2008  
Edition: 1



© Copyright 2008 Hewlett-Packard Development Company, L.P.

**Legal Notices**

*Hewlett-Packard makes no warranty of any kind with regard to this document, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Hewlett-Packard shall not be held liable for errors contained herein or direct, indirect, special, incidental or consequential damages in connection with the furnishing, performance, or use of this material.*

Confidential computer software. Valid license from HP required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

**Trademark Acknowledgments**

Unix® is a registered trademark of The Open Group.

This document provides information about the October 2008 release of the IEther-00 bundle for HP-UX 11i v3.

## 1 IEther-00 Overview

The IEther-00 bundle contains the `iether` version B.11.31.0810 driver, which supports the following Gigabit Ethernet cards and combination cards:

PCIe Gigabit Ethernet Cards	PCIe Gigabit Ethernet Mezzanine Cards	PCIe Combination Cards	PCI-X Gigabit Ethernet Cards	PCI-X Combination Cards
AD337A, AD338A, AD339A	NC360m, NC364m	AD221A, AD222A, AD393A	A7011A, A7012A, AB545A, AD331A, AD332A	AB290A, AD193A, AD194A

## 2 New and Changed Features in This Release

### 2.1 New Features

There are no new features included in IEther-00 at the time of this publication.

### 2.2 Changed Features

There are no changed features included in IEther-00 at the time of this publication.

## 3 Problems Fixed in This Version

Table 1 lists the problems fixed in this version of IEther-00.

**Table 1 HP-UX 11i v3 October 2008 Fixes — IEther-00 B.11.31.0810**

SR Number	Description
QXCR1000854397	On fiber cards with IEther-00 version B.11.23.0809 installed, performing any of the following actions might cause a LINK DOWN condition that persists until the system reboots: <ul style="list-style-type: none"><li>• Executing two or more resets with <code>lanadmin -r</code>.</li><li>• Performing multiple disable/enable cycles on the switch ports.</li><li>• Disconnecting and reconnecting the cabling.</li></ul>

The following table lists the problems fixed in recent versions of IEther-00.

**Table 2 HP-UX 11i v3 September 2008 Fixes — IEther-00 B.11.31.0809**

Reference Number	Description
QXCR1000771417	NC364m card port link flaps when the interconnect bay is empty.

## 4 Known Problems and Limitations

No known problems were identified for this version of IEther-00 at the time of this publication.

## 5 Compatibility and Installation Requirements

This section describes the compatibility information and installation requirements for this release.

- For specific installation instructions, see the installation procedure or overview document for your card.
- For detailed information on supported server platforms, operating systems, and firmware level requirements, see the *Ethernet System-Driver Matrix for HP-UX 11i v1, 11i v2, and 11i v3*.

These documents are available at:

<http://docs.hp.com/en/netcom.html>

## 5.1 Operating System and Version Compatibility

This release is specific for HP-UX 11i v3 (B.11.31).

## 5.2 Hardware Requirements

This version of IEther-00 runs on HP Integrity and HP 9000 servers with the HP-UX 11i v3 (B.11.31) operating system.

## 6 Related Information

The latest documentation for ethernet cards is available in English at:

<http://docs.hp.com/en/netcom.html>

## 7 Software Availability in Native Languages

The IEther-00 product is available only in the English language.