



HP Carrier-Grade Server cc3310 Reference RAID CARD Restrictions

Caution

There are known memory issues with the HP carrier-Grade Servers cc3310 and the Intel® RAID CONTROLLER: SRCZCR.

NOTE Refer to the current HP Server cc3310 user information at: http://www.hp.com/products1/servers/carrier_grade/products/cc3310/firmsoft_download.html

This caution note and additional Support Notes are available on the *HP Server cc3310 user information diagnostics and utilities resource* CD and at <http://docs.hp.com>. Search keyword cc3310.

